ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar

Street ID	Street Name	Significant Landmark
W0546, W0595, W0542, W0611, W0540	3rd Main Rd, 5th Crs, 1st Main Rd, NA	Kuvempunagara 2nd stage main road

Segment No.	Total Length (m)
11/S-W0546/S040001	255.71

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	74.38	77.539521	13.071415	77.540178	13.071222	W0611	W0633
2	74.16	77.538693	13.071347	77.539344	13.071143	W0611	W0595
3	107.17	77.538296	13.071115	77.539239	13.070827	W0611	W0555

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Road Development and Concrete road work at Kuvempunagara 2nd stage main road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zo	1999000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Road Development and Concrete road work at Kuvempunagara 2nd stage main road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000039

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-PMT/56/2015-16	28/04/2015	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
22/12/2015	21/12/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N KEERTHI		0.00

Phone No.	E-Mail ID
9731567144	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH
Date of Inspection	**Remarks**	
18/03/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	11	Ward Name:	Kuvempu Nagar	Street ID:	W0546, W0595, W0542, W0611,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	YARAPPA REDDY	18/03/2017	17/04/2017	COMPLETED
AEE	SHIVAKUMAR	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED